
## Assembly Instruction



(E) Insert corner table beam into 2 different seater beam and tighten with M10 X 75 csk allen cap screw and M10 hexagon nut.

Fix table supporter to round turn table with M6 X 16 csk m/c screw.

G Slot round turn table + table supporter and u-bracket lower into corner table beam and tighten with M10 X 70 allen cap screw.



