

# **Test Report**

#### No.: SDHG1501001521FT

Date: Feb.28, 2015

Page 1 of 7

MERRYFAIR CHAIR SYSTEM SDN BHD NO. 2, JALAN KORPORAT 1/KU9, TAMAN PERINDUSTRIAN MERU, KAPAR, 42200 SELANGOR, MALAYSIA.

The following sample(s) was / were submitted and identified on behalf of the client as:

Sample Description	:	FLITE CHAIR
Style / Item No.	:	557 B2 A00 J
Sample Receiving Date	:	Jan.28, 2015
Test Performing Date	:	Jan.28, 2015 to Feb.28, 2015

## **Test Result Summary**

Test(s) Requested	Result(s)
ANSI/BIFMA X5.4 - 2012	PASS
Summary:	

1. For further details, please refer to the following page(s).

Signed for and on behalf of SGS-CSTC Co., Ltd.

12m

Bill Wang Approved signatory





This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this documnt is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document be reproduced except in full, without prior written approval of the Company. A unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only .
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@gs.com

1/f;f<sup>1</sup>Building.European Industrial Park.No.15humhenan Road, Wusha Section,Daliang Town,Shunde,Foshan,Guangdong,China 528333 t (86-757)228058888 f (86-757)228058888 www.sgsgroup.com.cn 中国 ·广东 · 佛山市顺德区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层邮编: 528333 t (86-757)228058888 f (86-757)22805888 e sgs.china@sgs.com



# **Test Report**

No.: SDHG1501001521FT Da

Date: Feb.28, 2015

### **TESTS AND RESULTS**

#### **Test Conducted:**

ANSI/BIFMA X5.4-2012 Lounge and Public Seating – Tests, American National Standard for Office Furnishings.

#### **General Test Condition:**

The following test program was conducted in a laboratory environment maintained at  $15^{\circ}$  to  $25^{\circ}$  and  $50\%\pm5$  RH. The sample was individually tested after conditioning in the test environment for at least 24 hours prior to conducting the test.

The complete detailed procedures may be found in the referenced specification and are only summarized herein.

#### No. of Sample:

2 pieces (Sample 1 & 2). For more sample information and pictures, please refer to the following page.

Types of Lounge Seating: Multiple Seating (Type C). For the classification of types, please refer to Annex A.

Test	Test Description and Requirements	Test Results	
	Safety, Durability, and Structural Adequacy		
	<b>Back Strength Test - Horizontal Static - Functional Load</b> No loss of serviceability when 667N (150lbs.) is applied simultaneously for 1 min. Applied 90° to the back at 16in. above the seat.	PASS	
5	<b>Back Strength Test - Horizontal Static - Proof Load</b> No sudden and major change in the structural integrity (loss of serviceability is acceptable) when 1112N (250lbs.) is applied simultaneously for 1 min. Applied 90° to the back at 16in. above the seat.	PASS	
	<b>Back Strength Test - Vertical Static - Functional Load</b> No loss of serviceability when 890N (200lbs.) is applied simultaneously for 1 min. Applied to each backrest position.	/ Not applicable	
6	<b>Back Strength Test - Vertical Static - Proof Load</b> No sudden and major change in the structural integrity (loss of serviceability is acceptable) when 1334N (300lbs.) is applied simultaneously for 1 min. Applied to each backrest position.	/ Not applicable	
7	<b>Back Durability Test - Horizontal – Cyclic</b> No loss of serviceability in 120,000 cycles with a 102kg (225lbs.) in the center of each seat and a force of 334N (75lbf.) 90° to the backrest of each seating position.	PASS	
8	<b>Back Durability Test - Vertical – Cyclic</b> No loss of serviceability after applying a vertical downward force of 890 N (200 lbf) at the top of the backrest for 10000 cycles.	/ Not applicable	
9	<ul> <li>Arm Strength Test Horizontal –Static - Functional Load</li> <li>No loss of serviceability when apply horizontally inward and outward to the armrest at the most forward point of the armrest with the following force, for 1 min.</li> <li>For units with a distance between the arms less than 889 mm (35 in.), a force of 445 N (100 lbf.)</li> <li>For units with distance between the arms greater than or equal to 889 mm (35 in.), a force of 592 N (133 lbf.)</li> </ul>	/ Not applicable	



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document content be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only .

1/f;f<sup>4</sup>Building.European Industrial Park.No.1 Shumhenan Road, Wusha Section, Daliang Town, Shunde, Fostan, Guangdong, China 528333 t (86-757) 22805888 f (86-757) 22805888 www.sgsgroup.com.cn 中国 ·广东 · 佛山市順德区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层邮编: 528333 t (86-757) 22805888 f (86-757) 22805858 e sgs.china@sgs.com



Test Repor	rt No.: SDHG1501001521FT Date: Feb.28, 2015	Page 3 of 7
Test	Test Description and Requirements	Test Results
9	<ul> <li>Arm Strength Test Horizontal – Static - Proof Load</li> <li>No sudden and major change in the structural integrity (loss of serviceability is acceptable) when apply horizontally inward and outward to the armrest at the most forward point of the armrest with the following force, for 1 min.</li> <li>For units with a distance between the arms less than 889 mm (35 in.), a force of 667 N (150 lbf.)</li> <li>For units with distance between the arms greater than or equal to 889 mm (35 in.), a force of 890 N (200 lbf.)</li> </ul>	e / Not applicable
	<ul> <li>Arm Strength Test Vertical – Static - Functional Load         No loss of serviceability when apply the vertical load uniformly applie             along a 127mm (5in.) length at the apparent weakest point with th             following force, for 1 min.              </li> <li>For units with armrest width of greater than 75 mm (3 in.) a             force of 890 N (200 lbf.).             </li> <li>For units with an armrest width of less than or equal to 75 mm             (3 in.). a force of 750 N (169 lbf.).         </li> </ul>	e / Not applicable
10	<ul> <li>Arm Strength Test Vertical – Static - Proof Load</li> <li>No sudden and major change in the structural integrity (loss of serviceability is acceptable) when apply the vertical load uniforml applied along a 127mm (5in.) length at the apparent weakest point with the following force, for 1 min.</li> <li>For units with armrest width of greater than 75 mm (3 in.) a force of 1335 N (300 lbf.).</li> <li>For units with an armrest width of less than or equal to 75 mm (3 in.). a force of 1125 N (253 lbf.).</li> </ul>	y h /
11	<b>Arm Durability Test for Multiple Seat Units - Horizontal – Cyclic</b> There shall be no loss of serviceability when apply a 445 N (100 lbf.) force at an appropriate rate between 10 and 30 cycles per minute for 50,000 cycles.	/ Not applicable
12	<b>Arm Durability Test for Multiple Seating Units - Vertical – Cyclic</b> There shall be no loss of serviceability when apply a 667 N (150 lbf.) force at an appropriate rate between 10 and 30 cycles per minute for 10,000 cycles.	/ Not applicable
13	Arm Durability Test for Single Seat Units - Angular – Cyclic Simultaneously apply a force of 400 N (90 lbf.) to each arm initially at $10^{\circ} \pm 1^{\circ}$ degree angle for 60,000 cycles at a rate between 10 and 3 cycles per minute. There shall be no loss of serviceability to the unit.	
14	Seating Durability Tests – Cyclic No loss of serviceability after 100,000cycles impact. A weight of 57kg (125lbs.) free falls onto the seat from 3.6 in. height for each seating.	PASS
	<b>Drop Test – Dynamic - Functional Load</b> No loss of serviceability when 102kg (225lbs.) weight free falls from 6in. height to the center of the seat for each seating.	PASS
15	<b>Drop Test – Dynamic - Proof Load</b> No sudden and major change in the structural integrity (loss of serviceability is acceptable) when 136kg (300lbs.) weight free falls from 6in. height to the center of the seat for each seating.	n PASS



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms--Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 83071443, or email: CN.Doccheck@gsg.com

1/f;1<sup>4</sup>Building.European Industrial Park,No.1 Shurnhernan Road,Wusta Section,Daliang Town,Shurnde,Foshan,Guangdong,China 528333 t (86-757)22805888 f (86-757)22805888 www.sgsgroup.com.cn 中国・广东・佛山市順徳区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层邮编: 528333 t (86-757)22805888 f (86-757)22805888 e sgs.china@sgs.com



Test Rep	ort No.: SDHG1501001521FT Date: Feb.28, 2015	Page 4 of 7
Test	Test Description and Requirements	Test Results
	Leg Strength Test -Front Load - Functional Load No loss of serviceability when A force of 334 N (75 lbf.) is applied once to each front leg individually for one (1) minute.	PASS
16.3	Leg Strength Test -Front Load - Proof Load No sudden and major change in the structural integrity (loss of serviceability is acceptable) when A force of 503 N (113 lbf.) or a force equal to the weight of the entire unit, whichever is greater, is applied once to each front leg individually for one (1) minute.	PASS
	Leg Strength Test - Side Load - Functional Load No loss of serviceability when a force of 334N (75lbf.) is applied once to each front and rear leg individually for 1 minute.	PASS
16.4	Leg Strength Test - Side Load - Proof Load No sudden and major change in the structural integrity (loss of serviceability is acceptable) when A force of 503 N (113 lbf.) or a force equal to the weight of the entire unit, whichever is greater, is applied once to a front and rear leg individually for one (1) minute.	PASS
47	Unit Drop Test – Dynamic No loss of serviceability after lifting one end of the unit specified as below and allowing it to drop freely. Repeat a) on the opposite end of the unit.	PASS
17	Unit Weight         Drop Height           <45 kg (100 lbs.)	(180mm)
18.1	<b>Caster/Unit Base Durability Test for Pedestal Base Units</b> There shall be no loss of serviceability. The caster shall not separate from the base as a result of the application of the 22 N (5 lbf.) force after 500 cycles over a hard surface with obstacles and 25, 000 cycles over a smooth hard surface without obstacles under a 113kg (250lbs.) load on the seat. Test stroke is 762mm (30in.) minimum.	/ Not applicable
18.2	<ul> <li>Caster/Unit Frame Durability Test for Units with Legs         There shall be no loss of serviceability. The caster shall not separate from the base as a result of the application of the 22 N (5 lbf.) force after the following tests under a 113kg (250lbs.) load on the seat. Test stroke is 762mm (30in.) minimum.         For single seating units, the unit, or unit's frame with casters, shall be cycled for 500 cycles over the obstacles and then 25,000 cycles on a smooth hard surface without obstacles.         Multiple seating units shall be cycled 250 cycles over the obstacles.     </li> </ul>	/ Not applicable
19	Swivel Test – Cyclic No loss of serviceability after 120,000 cycles of rotation (360°) under a 113kg (250lbs.) load on the seat.	/ Not applicable
20	<i>Tilt Mechanism Test – Cyclic</i> No loss of serviceability after 200,000 cycles under a 102kg (225lbs.) load to the center of the seat	/ Not applicable



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms--Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 83071443, or email: CN.Doccheck@gsg.com

1/f;1<sup>4</sup>Building.European Industrial Park,No.1 Shurnhernan Road,Wusta Section,Daliang Town,Shurnde,Foshan,Guangdong,China 528333 t (86-757)22805888 f (86-757)22805888 www.sgsgroup.com.cn 中国・广东・佛山市順徳区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层邮编: 528333 t (86-757)22805888 f (86-757)22805888 e sgs.china@sgs.com



Test Repor	rt No.: SDHG1501001521FT Date: Feb.28, 2015	Page 5 of 7
Test	Test Description and Requirements	Test Results
21.3	<ul> <li>Stability Test - Rear Stability for Non-tilting Units Load the seat (or, for multiple seat units, load the seat of one of the seating positions) with 6 disks. Apply a horizontal force to the highest disk. The location of the force application is 6 mm (0.25 in.) from the top of the disk. For units with seat height (as measured at the front of the bottom of the lowest disk when all disks are in the unit) less than 710 mm (28.0 in.), calculate the force as follows: F = 0.1964 (1195 – H) Newton. H is the seat height in mm. For units with seat height equal to or greater than 710 mm (28.0  in.), a fixed force of 93 N (20.9 lbf.) shall be applied.</li></ul>	PASS
21.4	The application of the force shall not cause the unit to tip over. <b>Stability Test - Rear Stability Test for Tilting Units</b> Load one seat position with 13 disks. If the unit does not tip over and the tilt mechanism does not tilt to its most rearward position (i.e., at its tilt stop) when the disks are placed in the seat, the unit shall also be tested according to 21.3.1 with the unit in the unlocked position. The application of the force shall not cause the unit to tip over.	/ Not applicable
21.5	<b>Stability Test - Front Stability</b> A downward force shall be applied initially at 45° to the test platform by attaching a strap centered over the front portion of the seat. The force shall be applied until the total unit weight is transferred to the front support members. The force shall not be less than 40% of the unit weight.	PASS
22	<b>Tablet Arm Load Ease Test – Cyclic</b> No loss of serviceability to the unit after a 343 N (77 lbf.) force applied through a 203 mm $\pm$ 13 mm (8.0 in. $\pm$ 0.51 in.) diameter area centered on the writing area of the tablet for a total 100,000 cycles.	/ Not applicable
23	<b>Tablet Arm Static Load Test</b> Apply a load of 68 kg (150 lb) at the apparent weakest position for 1 minute and remove the load. The load applied once shall cause no sudden and major change in the structural integrity of the unit. After performing the test, the tablet arm must allow egress from the unit; other losses of serviceability are acceptable.	/ Not applicable

#### Annex A: Classification of Types of Lounge Seating

Single Seating	Multiple Seating
Style A - with arm(s) and with backrest	Style A - with arm(s) and with backrest(s)
Style B - with arm(s) and without backrest	Style B - with arm(s) and without backrests
Style C - without arms and with backrest	Style C - without arms and with backrest(s)
Style D - without arms and without backrest	Style D - without arms and without backrests

#### Remark:

1. For the sample information and pictures, please refer to the following page.



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-enDocument.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document, subject to Terms and Conditions for Electronic the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only . Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN\_Doccheck@sgs.com

1版;<sup>15</sup>Building.European Industrial Park,No.1Shumheran Road,Wusta Section,Dalang Town,Shunde,Foshan,Guangdong,China 528333 t (86-757)22805888 f (86-757)22805858 www.sgsgroup.com.cn 中国・广东・佛山市順徳区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层邮编: 528333 t (86-757)22805888 f (86-757)22805858 e sgs.china@sgs.com



## Test Report No.: SDHG1501001521FT

Date: Feb.28, 2015

Page 6 of 7

#### SAMPLE INFORMATION AND PICTURES

Weight: 31.00kg

Overall Dimensions: 1443mm L x 685mm W x 804mm H

Other Dimensions: /

#### Sample as Received



View 3

View 4



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document aspx. Attention is drawn to the limitation of liability, is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document to the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

1/fr,f\*Building.European Industrial Park,No.1Shunhenan Road,Wusta Section,Daliang Town,Shunde,Fristran,Guangdorng,China 528333 t (86-757)22805888 f (86-757)22805858 www.sgsgroup.com.cn 中国 ·广东 · 佛山市順德区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层 邮编: 528333 t (86-757)22805888 f (86-757)22805858 e sgs.china@sgs.com



# **Test Report**

No.: SDHG1501001521FT

## Date: Feb.28, 2015

Page 7 of 7





\*\*\*End of Report\*\*\*



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms--Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 83071443, or email: CN\_Doccheck@sgs.com

1/f;1<sup>4</sup>Building.European Industrial Park,No.1Shuriheraa Road,Wusha Section,Dalang Town,Shurude,Foshan,Guangdoing,China 528333 t (86-757)22805888 f (86-757)22805888 www.sgsgroup.com.cn 中国・广东・佛山市順徳区大良街道办事处五沙顺和南路1号欧洲工业园一号厂房首层邮编: 528333 t (86-757)22805888 f (86-757)22805858 e sgs.china@sgs.com